Hefringer/KM REC'D JUL 1 0 2003

Weiler Corporation

One Wildwood Dr., Cresco, PA 18326

• Information Requests: (888) 600-5857 - (570)

595-7495

5 Fax: (570) 595-2002

DE-mail: info@weilercosp.com

MSDS

Stainless Steel Wire Brushes

Section I

Manufacturer's Name: Weiler Corporation

Address: One Wildwood Drive, Cresco, PA 18326 Emergency Telephone Number: (570) 595-7495 Telephone Number for Information: (570) 595-7495

Date prepared: September 27, 1996 Name of preparer: Frank J. Hettes

Section II - Hazardous Ingredients / Identity Information

Hazardous Components, (Specific Chemical Identity, Common Name (8)	CAS#	OSHA PEL	ACGIH TLV		Listed	WT %
Iron	7439-89-6	None	None	No	No	48-89
Chromium	7440-47-3	1.00	0.50	Yes	Yes	10-27
Nickel	7440-02-0	1.00	1.00	No	Yes	0-35
Manganese	7439-96-5	C5 (6)	C5	No	No	0-1\5
Tungsten	7440-33-7	None	5.00	No	No	0-4
Molybdenum	7439-98-7	15.0	10.00	No	No	0-4
have a second of the second of	7429-90-5	None	10.00	No	No	0-2
Copper	7440-50-8	1.00	1.00	No	No	0-4
Silicon	7440-21-3	None	10.00	No	No	0-5
Cobalt	7440-48-7	0.10	0.05	No	No	0-5

Section III - Physical / Chemical Characteristics

Boiling Point: *N/A

Vapor Pressure (mm Hg.): *N/A Vapor Density (AIR=1): *N/A

REC'D JUL 1 0 2003

Solubility in Water: *N/A Specific Gravity (H₂O=1): 7

Melting Point: *N/A

Evaporation Rate (Butyl Acetate=1): *N/A

Appearance and Odor: Bright silver metal; odorless

Section IV - Fire and Explosion Hazard Data

Flash Point (method used): *N/A

Flammable Limits: *N/A LEL: *N/A UEL: *N/A

Extinguishing Media: *N/A

Special Fire Fighting Procedures: *N/A

Unusual Fire and Explosion Hazards: None known

Section V - Reactivity Data

Stability: Stable

Incompatibility (Materials to Avoid): None

Hazardous Decomposition or Byproducts: Metal fumes - iron oxide, manganese, nickel,

chromium, molybdenum, copper, vanadium, pentoxide.

Hazardous Polymerization: Not known

Section VI - Health Hazard Data

Routes of Entry	Solution
Inhalation	Wear approved respirator.
Eyes	Wash eyes with water, seek medical attention.
Ingestion	Seek medical attention.
Clothing	Wash clothing.
Skin	Wear eye protection and protective clothing.

Carcinogenicity: Not known

Signs and Symptoms of Exposure: Not known

Medical Conditions Generally Aggravated by Exposure: Not known

Emergency and First Aid Proceedures: Wash skin with soap and water; seek medical attention.

Section VII - Precautions For Safe Handling And Use

Steps to be taken in case material is released or spilled: *N/A

Waste disposal method: Dispose of in accordance with EPA or local regulations.

Precautions to be taken in handling and storage: *N/A

Other Precautions: Welding and cutting - use adequate ventilation and approved respirator.

Section VIII - Control Measures

Respiratory protection (specify type): Use approved NIOSH respirator. Ventilation:

REC'D JUL 10 2003

Local Exhaust: Use when welding or cutting.

Special: Depending on use, consult local, state and federal codes for appropriate selection.

Mechanical (General):

Protective gloves: Wear gloves.

Eye protection: Wear eye protection.

Other protective clothing or equipment: Wear protective clothing.

Work/Hygienic Practices: Keep work area clean.

*N/A = Not applicable

Brushes, Abrasives and more....



Who Is Weiler? • What's New? • What We Make • Application Assistance • Safety Info
Literature • Videos • Contact Info • Weiler Distributors • Employment Opportunities • Copyright Info ISO 9001 Certification Directions To Weiler Corporation Product Cross Reference

© Copyright 2001 Weiler Corporation, All Rights Reserved.